



Photo 1: Erosion of general fill into constructed swale, adjacent to MDNRE property - Facing South



Photo 2: Erosion of general fill into constructed swale along northern MDNRE property boundary - Facing East





Photo 3: Wash-out to the Kalamazoo River following Monday Rain Event - Facing East



Photo 4: Wash-out to the Kalamazoo River following Monday Rain Event - Facing South





Photo 5: Wash-out to the Kalamazoo River following Tuesday Rain Event - Facing East



Photo 6: Wash-out into the Kalamazoo River following Tuesday Rain Event - Facing South





Photo 7: Erosion channel and wash-out area on northwest side slope of landfill - Facing Southeast



Photo 8: Erosion channel on north-central side slope of Site - Facing South





Photo 9: Another erosion channel on north-central side slope of Site – Facing South



Photo 10: Erosion channels along west side of Site – Facing South





Photo 11: Erosion channels along west side of Site - Facing Southeast



Photo 12: Close-up of erosion channels along the central-west side slope - Facing East





Photo 13: Erosion channels along southwest side slope of Site - Facing South



Photo 14: Top view of typical erosion channel along southwest side slope - Facing West

